


# WOODBURY SALTERTON RESILIENCE GROUP

**Honey Lane**  
Between Honey Cottage and Cycle Way.  
 Food water coming off fields and flooding road  
 Requires Engineering  
 Drains in Honey Cottage side and drains into ditch by Cycle Way

**Village Road**  
Church Lichgate  
 drains on either side not coping  
 Requires Engineering  
 its only a small pipe draining through the church yard to the stream.

**Village Road**  
Outside Tamarisk  
 pipe blowing under tarmac.  
 Manhole lifting.  
 Requires Engineering  
 larger bore pipe

16.05.2021  
 Woodbury Salterton  
 Resilience Group



**Honey Lane 100 from junction**  
 The ditch was dug out a few years ago and this is now working well

**Honey Lane ford bridge**  
 Cannot do anything to stop flooding here  
 Suggestion put a high indicator and "Ford Signs" may assist

**White Cross Road**  
 This is a field entrance and runoff coming off field. However there is a ditch inside the field to a pipe that takes flood water under road, which is not large enough  
 Requires Engineering, kerb at entrance to field. Larger pipe under road

**Dog Lane junction Whitecross Road**  
 Surface water flowing off field across Road and down Stony Lane  
 Change in field gate position?

**Toby Lane**  
 The ditches are running well until entrance to bungalow where a pipe takes the flow under and across the road but is blocked.  
 However taking the stormwater from there is problematic as the ditch then goes through a number of residential gardens and a different solution needs to be found  
 Ideally we need to slow and reduce the flow to help reduce the flow downstream



White Cross Road Woodbury Salterton  
 Surface water flowing off field.  
 There is a ditch on the field side of the hedge is could go into.



Water is about 8 inches  
 Deep so not as high as previously



The tarmac continually lifts  
And recently a large patch  
was inserted

However the pipe restriction  
Was not sorted and its lifted again



Outside Tamarisk  
Village Road  
Woodbury Salterton

This manhole continually blows  
During a flood event



The tarmac is braking up

### Report from the Woodbury Salterton Resilience Group

There were no properties flooded and the stream through the village was about 100mm from the top of the culvert at the school at the height of the flood event. Well below the level which would lead to property damage.

The improved flow of the stream through the village is mostly down to various small engineering works carried out by the Resilience group to reduce pinch points and the yearly stream clearance volunteers carry out each year.

All the roads where possible with care but several vehicles were sensible by turning around on Whitecross Road when the flooding there was at its height.

There are several drains that are not operating but the only ones causing a serious problem to the highway was the 2 on either side of Village Road at the near the church lichgate. This has been identified as a problem for some years.

However, the area that is a concern to residents is Toby Lane becomes a torrent of water from Toby Cottage all the way down the hill to Whitecross Road. During the winter this becomes an ice rink and several pedestrians and cyclists have fallen, but none seriously. A solution for this is being investigated.

The other main issue is the continuous problem outside Tamarisk on Village Road. The problem is not totally clear, but it is suspected that the entry pipe is larger than the exit pipe and the water forces the road surface to raise and then brakes up. As this is a bus route this is the most urgent work required and Devon CC Highways and County Councillors are aware of the problem